

JOHN AND MARY FELDERMAN FARM, MILKING BARN
Northeast Corner of County Road 56.
and County Road T
Clarkville Vicinity
Yuma County
Colorado

HABS NO. CO-129-K

HABS
COLO
63-CLK.V,
1K-

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDING SURVEY

JOHN AND MARY FELDERMAN FARM
MILKING BARN

HABS NO. CO-129-K

HABS
COLO
63-CLK.V,
1K-

Location: Southwest 1/4 of the Southwest 1/4 of Section 22, Township 5 North, Range 46 West, Sixth Prime Meridian. Yuma County, Colorado. North of the intersection of County Road 56 and County Road S, vicinity of Clarkville, Colorado.

Present Owner: Farmers Home Administration, U.S. Department of Agriculture

Present Occupant: Vacant

Present Use: None

Milking Barn

Exterior

This building, directly west of the barn, was constructed in 1974. It is of concrete block construction with a 2x4 wood frame roof and a concrete foundation. It is one story tall and rectangular in shape. The gable roof is covered with corrugated metal sheets. The roof's gable ends are unpainted plywood panels. There are two overhead tracked sliding doors and a pair of one light over three panel wood doors that appear to have been salvaged from another building. The windows are one by one light aluminum framed sliding windows set in prefabricated steel frames. On the south side are the remains of a wood pole framed storage shed that was covered with corrugated metal panels at one time.

Interior

The interior is unfinished except for a coat of paint on the concrete blocks. The interior partition walls are framed with 2x4s and covered in plasterboard and fiberboard. These also are painted. There are five interior rooms: the milking parlor, the milk storage room, a medicine and chemical storage room, a utility area and a toilet.

Existing Condition

The building is in good condition.